




Application Note

Electromechanical Automation Europe
Application Team Offenburg




aerospace
climate control
electromechanical
filtration
fluid & gas handling
hydraulics
pneumatics
process control
sealing & shielding



PSD - Communication

ControlManager FB50 for TIA-Portal



Author: K. Woloschin
Application: PSD_Comm_AN0030
Version: V1.1
Last change: 10 February 2017



ENGINEERING YOUR SUCCESS.



PSD - Communication

Warranty Disclaimer

While efforts were made to verify the accuracy of the information contained in this documentation, Parker expressly disclaims all warranties with regard to this application note, including, but not limited to, the implied warranties of merchantability and fitness of a particular purpose. Parker does not warrant, guarantee, or make any representation regarding the use or the results of the use of this application note in terms of correctness, accuracy, or reliability. The contents of this application note are subject to change without notice. Parker will publish updates and revisions of this document as needed. The documents supersedes all previous versions.

Limitation of Liability

You agree that Parker shall not be liable to you under this agreement for any damages, including without limitation any lost profits, or any consequential, incidental, or punitive damages arising out of the use or inability to use this application note and related documents, or for any claim by another party. You agree and hold Parker harmless for all claims and damages from any third party as a result of their use or inability to use any product that you develop based on this application note and the products and/or services documented herein.

Parker Hannifin Manufacturing Germany GmbH&Co.KG

Electromechanical Automation Europe

Business Development & Applications

Copyright © 2010 - 2017

All rights reserved.



ENGINEERING YOUR SUCCESS.



PSD - Communication

Table of Contents

1. DEVICE SUPPLEMENT	3
1.1. With the option.....	3
1.2. And the master plc	4
2. PURPOSE OF THE BLOCK	4
2.1. Overview	4
2.2. Restrictions and application.....	4
2.3. History of modifications	4
3. SETTING UP	5
3.1. PSD configuration.....	5
3.2. SIMATIC - HW Config.....	5
3.3. Application interface of "PSDControlManager".....	7
4. APPLICATION EXAMPLE	13
4.1. Overview of the connection:	13
4.2. Cyclic channel (PD_IO).....	14
4.3. Acyclic channel (PKW).....	15
4.4. Parameter channel	15

1. Device supplement

1.1. With the option

- PSD1S....B2





PSD - Communication

- PSD1M...B2

1.2. And the master plc

- SIMATIC S7-1500
- SIMATIC S7-1200

2. Purpose of the Block

2.1. Overview

Absolute	Symbol	Comment	Vers	Date	Device	Application
FB50	C3ControlManager For TIA -Portal	PSD1..B2 ControlManager	1.1	2017-02-07	PSD	Positioning, absolute / relative

2.2. Restrictions and application

This block simplifies the control of a PSD DRIVE (with PROFIdrive profile) with the S7. The block needs the commands and set values. The block distributes messages and actual values from the drive. The channels PZD and PKW are used in both directions.



This block is only usable with PPO14 (APA_IO = 8BYTE, PD_IO = 18BYTE)

2.3. History of modifications

V1.1 2017-02-07 First version



ENGINEERING YOUR SUCCESS.



PSD - Communication

3. Setting up


3.1. PSD configuration

With PSDServoManager perform following adjustments:

PROFINET-Settings	
Selected Operation mode	2 Positioning mode with submode MDI (Manual Data Input)
Acyclic Parameter Access (APA)	ParameterChannel_4words
FBI timeout 0x7583	Stop_drive_disabled
PROFINET-Mapping	
APA_IO [16bit words]	4
PD_IO [16bit words]	9
R-PDO: 9 words	
RPDO 1	0x6040.0 Control word 1 (STW1, PNU 967) [16b]
RPDO 2	0x607A.0 MDI target position (MDI_TARPOS) [incr] [32b]
RPDO 3	0x6081.0 MDI velocity (MDI_VELOCITY) [incr/s] [32b]
RPDO 4	0x6083.0 MDI acceleration [incr/s ²] [32b]
RPDO 5	0x6084.0 MDI deceleration [incr/s ²] [32b]
T-PDO: 9 words	
TPDO 1	0x6041.0 Status word 1 (ZSW1, PNU 968) [16b]
TPDO 2	0x6064.0 Position actual value A (XIST_A) [incr] [32b]
TPDO 3	0x606C.0 Speed actual value B (NIST_B) [incr/s] [32b]
TPDO 4	0x0007.0 DummyObj_32Bit [32b]
TPDO 5	0x0007.0 DummyObj_32Bit [32b]

3.2. SIMATIC - HW Config


Add PSD device from Hardware catalog



ENGINEERING YOUR SUCCESS.

PSD - Communication

Assign IP-address and device name. Check device module configuration (APA_IO =4 words, PD_IO = 9 words).




Edit HardwareID of APA_IO and PD_IO modules (here 265 PZD and 267 PKW) in Instance Variable.


Adjust hardware identifier for APA_IO in <nLaddrPKW> (DB50.DBW8).



PSD - Communication



Adjust hardware identifier for PD_IO in <nLaddrPZD> (DB50.DBW6).



3.3. Application interface of "PSDControlManager"

3.3.1. Schematic drawing for in- and output Areas of FB50 / DB50



ENGINEERING YOUR SUCCESS.

PSD - Communication

in <input type="checkbox"/> input	out <input type="checkbox"/> output	in_out <input type="checkbox"/> In- and Output	stat <input type="checkbox"/> Static Memory
-----------------------------------	-------------------------------------	------------------------------------------------	---------------------------------------------

DB50

	EN	ENO	
DBX0.0	bEnable	bEnabled	DBX2.0
DBX0.1	bAbsoluteRelative	bDriveErr	DBX2.1
DBX0.2	bPositionResetMode	bPosRunning	DBX2.2
DBX0.3	bHold	bInPosition	DBX2.3
DBX0.4	bStop	bPosErr	DBX2.4
DBX0.5	bFaultReset	bHomingRunning	DBX2.5
DBX0.6	bJogP	bHomingAttained	DBX2.6
DBX0.7	bJogN	bHomingErr	DBX2.7
DBX1.0	bExDataTransfer	bCommErr	DBX3.0
DBX4.0	bStartPositioning		
DBX4.1	bChangeSetImmediate	stRd.iPositionValue	DBD46
DBX4.2	bStartHoming	stRd.iVelocityValue	DBD50
DBW6	nLaddrPZD	stRd.nActualError	DBW54
DBW8	nLaddrPKW		
DBD10	iPosition		
DBD14	iVelocity		
DBD18	iAcceleration		
DBD22	iDeceleration		
DBD26	iInPosWindowAbs		
DBW30	nCmd	bTransErr	DBX3.1
DBW32	nObjectIndex		
DBW34	nObjectSubindex		
DBD36	iParameterValue	iParameterValue	DBD34
DBD40	TonTimer1		
DBD44	TonTimer2		
DBX56.0 Word 4	stC3PKWInDint.nPKE	stC3PKWOutDint.nPKE	DBX64.0 Word 4
DBX72.0 Word 7	stC3PZDIn.nStatus	stC3PZDOut.nControl	DBX86.0 Word 7

3.3.2. Declaration of In- and Output

PSD - Communication

Parameter	Declaration	Data type	description
bAbsoluteRelative	IN	BOOL	=0 absolute, =1 relative movement
bEnable	IN	BOOL	=1 energise =0 disenergize with AUS3 - Ramp (Not-Stop)
bExDataTransfer	IN	BOOL	=0 internal DP interface with DPWR_DAT/DPRD_DAT (internal Master in S7 CPU) =1 external DP interface with FC2/FC1 (external Master CP 342-5)
bFaultReset	IN	BOOL	Acknowledge with rising edge, after that it is necessary to activate energise <bEnable> (caused by the edge detection it is needed to be set to 0 first)
bHold	IN	BOOL	=1 Temporary stop (the movement function is still available), =0 continue
bJogN	IN	BOOL	manual negative: JOG – movement within positioning end limits as long as true
bJogP	IN	BOOL	manual positive: JOG – movement within positioning end limits as long as true
bPositionResetMode	IN	BOOL	=0 Normal-, =1 Reset mode selected (in C3Mgr \\ I20T11 drive Configuration \units... positioning reset distance and positioning reset distance denominator is different from 0 (Not supported with PSD drives yet))
bStop	IN	BOOL	=1 Stop (movement function cancelled)
bChangeSetImmediate	IN_OUT	BOOL	With the Rising edge, a new position profile is activated; <bChangeSetImmediate> is reseted from the block itself. This command is acknowledged from the block with <bPosRunning>. A new command is also accepted if the actual movement is not finished (<bInPosition> =1). (Not supported with PSD drives yet)
bStartHoming	IN_OUT	BOOL	rising edge starts referencing movement, if permitted, neg. edge stops referencing movement, bStartHoming may only be reseted with <bHomingAttained>.
bStartPositioning	IN_OUT	BOOL	With the Rising edge a new position profile is activated, <bChangeSetImmediate> is reseted from the block itself. This command is acknowledged from with <bPosRunning>. A new command is not

PSD - Communication

Parameter	Declaration	Data type	description
			accepted if the actual movement is not finished (<bInPosition> =1).
bCommErr	OUT	BOOL	=1 communication failure (Failure from DPWR_DAT / DPRD_DAT) (all other messages are invalid)
bDriveErr	OUT	BOOL	=1 failure from PSD (device / motor)
bEnabled	OUT	BOOL	=1 Axis energised =0 Axis not energised
bHomingAttained	OUT	BOOL	=1 reference ok.
bHomingErr	OUT	BOOL	=1 watchdog/ timeout for Reference -run (occasionally TonTimer2 correct)
bHomingRunning	OUT	BOOL	=1 reference run active
bInPosition	OUT	BOOL	=1 axis in target position
bPosErr	OUT	BOOL	=1 watchdog timeout for position -order (occasionally. TonTimer1 correct)
bPosRunning	OUT	BOOL	=1 position or active
bTransErr	OUT	BOOL	=1 format-, command failure at transfer from / to PSD
iAcceleration	STATIC	DINT	acceleration in U32 -Format (integer)
iDeceleration	STATIC	DINT	deceleration in U32 -Format (integer)
iInPosWindowAbs	STATIC	DINT	Position window in additional monitoring of <bInPosition> with absolute positioning. The actual position value compared with the position set value. That is only possible with absolute positioning (<bAbsoluteRelative> = false) and position Reset mode (<bPositionResetMode> = false) is not activated.
iParameterValue	STATIC	DINT	PSD object value (source and destination) - write-/read value of the Parameters, with INT/WORD - format only one word used.
iPosition	STATIC	DINT	target position / distance in increments
iVelocity	STATIC	DINT	speed in increments
stRd.iPositionValue	STATIC	DINT	actual position in increments
stRd.iVelocityValue	STATIC	DINT	actual speed in increments
nCmd	STATIC	INT	PSD object transfer: command: 1 read

PSD - Communication

Parameter	Declaration	Data type	description
			2 write WORD 3 write DWORD
nObjectIndex	STATIC	INT	PSD object index
nObjectSubindex	STATIC	INT	PSD object subindex
TonTimer1	STATIC	TIME	time value for timeout of Positioning
TonTimer2	STATIC	TIME	time value for timeout Reference run
nLaddrPZD	STATIC	WORD	= 0100 _{hex} (=256 _{dez}) Hardware identifier of the (PD_IO) Process Data module.
nLaddrPKW	STATIC	WORD	= 0100 _{hex} (=256 _{dez}) Hardware identifier of the APA_IO (Acyclic Parameter Access) data module.
stRd.nActualError	STATIC	WORD	Actual Failure (see PSD - Manual) in WORD - Format =1 no Error!
stPSDPKWInDint.nPKE	STATIC	Word 4	Local PKW - input area for external CP
stPSDPKWOutDint.nPKE	STATIC	Word 4	Local PKW - output area for external CP
stPSDPZDIn.nStatus	STATIC	Word 9	Local PZD - input area for external CP
stPSDPZDOut.nControl	STATIC	Word 9	Local PZD - output area for external CP

3.3.3. Sequence of process data

3.3.3.1. Settings of the static Operands at the Block

1. <nLaddrPZD>and<nLaddrPKW>

- Parameter from (System constants): HW-ID of the IO-device for PZD and PKW channel.
- Forward the values to <nLaddrPZD> and <nLaddrPKW>.

2. <bExDataTransfer>

- Low: settings for CPU with integrated Master
- High: settings for CPU with external Master



PSD - Communication

3. *<iInPosWindowAbs>*
 - additional control window for the message *<bInPosition>*
4. *<TonTimer1>*
 - Time value for watchdog positioning, if this time is too short there is shown the error message *<bPosError>*.
5. *<TonTimer2>*
 - Time value for watchdog homing, if this time is too short there is shown the error message *<bHomingErr>*.

3.3.3.2. Settings of dynamic Operands at the Block

1. Switch on

- Set *<bEnable>*: the block notifies *<bEnabled>*
- Set *<bStartHoming>*, the block notifies *<bHomingRunning>*. If the homing finished, the block notifies *<bHomingAttained>*.
- Now reset *<bStartHoming>*.
- At reaching home position, the message *<bInPosition>* is set.
- With some home modes (e.g. MN-M 35) and high velocity *<bHomingRunning>* is set so short, that is not visible.
- If there is a motor with absolute position feedback (SinCos©), it is only one time needed to activate homing. *<bHomingAttained>* remains at True even if the drive is switch off and on again. Attention: With activating, the homing from PSD-Optimisation *<bHomingAttained>* is not set.

2. Positioning

- Set Parameters for Positioning
- *<bAbsoluteRelative>*
- *<iPosition>*
- *<iVelocity>*
- *<iAcceleration>*
- *<iDeceleration>*
- Start the positioning with activating : *<bStartPositioning>*
- *<bStartPositioning>* is reseted by the block itself
- The block notifies *<bPosRunning>*
- With reaching the target position, die message *<bInPosition>* is set.
- A new target position is only possible after *<bInPosition>* was set.

3.3.3.3. Other Operands at Block

- *<bFaultReset>* acknowledgement of failures of function block (watchdog) or drive (PSD).
- *<bStop>* stops a positioning with rising edge
- *<bHold>* interrupt of positioning command, as long as Bit it is *true*; positioning will be finished when the bit is *false* again.





PSD - Communication

- <bJogN> manual mode negative direction, as long as Bit it is *true*.
- <bJogP> manual mode positive direction, as long as Bit it is *true*.

3.3.3.4. Messages and display

- <bCommErr> communication with PSD not possible
- <bDriveErr> PSD is in failure status
- <stRd.nActualError> actual Failure number of PSD (see C3 Help)
- <stRd.iPositionValue> actual position
- <stRd.iVelocityValue> actual velocity

3.3.3.5. Read and write drive objects

- the objects are selected with <nObjectIndex> and <nObjectSubindex>
- the value is at <iParameterValue>
- *nCmd* is the command for the transfer
 - 1 command for read
 - 2 command for write word parameter (16 Bit)
 - 3 command for write double word Parameter (32 Bit)Datatype 16 Bit or 32 Bit is shown in the object info “Bus format”.
- <bTransErr> shows if there is failure with the data transfer.

4. Application example


4.1. Overview of the connection:

Connection between one PLC SIMATIC S7 1500 as IO-CONTROLLER and one drive PSD as IO-DEVICE.



ENGINEERING YOUR SUCCESS.

PSD - Communication



4.2. Cyclic channel (PD_IO)

The in- and output objects are selected in the PSD servo manager wizard. All tags are either word or double word format. The settings are instructed in the following order to assure the FB is working.


S7	= >	PSD	= >	S7
In			Out	
DBB86	0	STW1		DBB72
DBB87	1			DBB73
DBB88	2	Position set point value A XSOLL_A	ZSW1 Actual position Value XACTUAL_A	DBB74
DBB89	3			DBB75
DBB90	4			DBB76
DBB91	5			DBB77
DBB92	6	Commande d motion speed NSOLL_D	Actual speed Value NACTUAL_B	DBB78
DBB93	7			DBB79
DBB94	8			DBB80
DBB95	9			DBB81
DBB96	10	Set point acceleration B		DBB82
DBB97	11			DBB83
DBB98	12			DBB84
DBB99	13			DBB85

PSD - Communication



4.3. Acyclic channel (PKW)

Via the 8 Byte APA_IO interface the user is able to transfer additional objects to or from PSD. The block is using this interface to transfer Failure number.



4.4. Parameter channel

The PLC (HMI) is asking for the value of actual torque [683.1]

Also the value of stiffness [2100.2] should be changed. The procedure is explained with help of SIMATIC Variable table.

4.4.1. Used area

	FB50		
DBW28	nCmd	bTransErr	DBX3.1
DBW30	nPNUIIndex		
DBW32	nPNUSubindex		
DBD34	iParameterValue	iParameterValue	DBD34

4.4.2. Procedure for reading and writing of current limit positive object [0x3210.0]

1. Open Object Tree → object info:



PSD - Communication

PSD Object Tree <dev> 20170210_100212 // 156ms

Object	0x3210.0
Name (cache)	PosCurrentConfigAxis1
Name (db)	PosCurrentConfig
NameSpace	Axis1.SupervisionA.Limit.CurrentL.PosCurrentConfig
DS402 range	PH PSD Axis1 0x3000..0xFFFF
Datatype	UINT16
RawDataType	None
Flags	I E W MM
Min value	0
Max Value	0

- Set requested object index and subindex:

nObjectIndex <3210>
 nObjectSubindex <0>

- Next edit the command for "read" (1) !

nCmd <1>

- Check object value

iObjectValue e.g.<2000>

- Next set new object value

iObjectValue e.g.<1000>

- Edit new command for "write 16b" (2) !

nCmd <2>

- Verify the result in PSD ServoMgr (object value 0x3210.1).





PSD - Communication



Caution:

VP and WF use system resources, which decrease the effectiveness of internal communication. This may have the effect that there occur error messages like „cycle time overrun“. So you should use these two commands not too often.

Try to use them during the axis is not energized. It would be better to change first a couple of parameters and activate them together by writing VP only one time.



ENGINEERING YOUR SUCCESS.